

Lakeside Park Water System Activity Summary April 2007

Water Treatment:

Booster Pump electrical control failure. Hatch Electric replaced circuit breaker

Semiannual electrical controls done by Hatch Electric

Added another operator to help out on summer time projects

Responded to several alarms due to pressure drops in the water distribution system caused by the project 3 contractors

Replaced Fuse in Fire Pump Control

Tested and exercise emergency power generation system

No treatment failures occurred during this time period

All water produced met safe drinking water standards

Water Distribution:

Continued work in the Project 3 area. Locating and marking water lines and service connections. Remarkd all lines for contractor and reviewed old plans for additional water lines that might be in construction area and marked

Repaired damaged ballards and valve vault for fire hydrant located at Popular and Cedar. Repairs made by Rick Martin Construction. Damage looks to have been caused by a snow plow. SLT Police had no accident report on file.

Found and dug up service valves for Sierra Tee Shirt building

Started water system valves annual exercising and vault cleaning.

Miscellaneous:

Misc. USA locates

Administration:

Submitted April Monitoring report and 1st Quarter Disinfection By Product Rpt
Attended Project 3 Meetings