

# **Lakeside Park Water System Activity Summary May 2007**

## **Water Treatment:**

Chlorine feed system leak; made temporary repairs then built replacement manifold.

Tested and exercise emergency power generation system

No treatment failures occurred during this time period

All water produced met safe drinking water standards

## **Water Distribution:**

Continued work in the Project 3 area. Inspected contractor's work when exposing LPA's water lines to insure they are not damaged during excavation. At times they were scraped and we had to make protective coating repairs. Contractor hit 2 water service connections going to the Block Motel. Repairs were made by the contractor under our supervision.

Disconnected water service to Java Hut building. Main still active to supply Mac P's and new sales office.

Worked with contractor to hook-up water service to remaining Holiday Lodge buildings.

Repaired 6" main leak on Sunrise – Rick Martin

Dug up and disconnected several water services on Cedar where buildings had already been demoed.

Replaced temporary street patches with asphalt at winter time repair sites – Rick Marti

**Miscellaneous:**

Misc. USA locates

**Administration:**

Submitted May Monitoring report  
Submitted 2006 Annual Report to DOHS