

Lakeside Park Water System Activity Summary January 2010

Water Treatment:

Bacteria sampling.

Plant Maintenance

Tested and exercise emergency power generation system

Responded to various alarms and corrected.

All water produced met safe drinking water standards

Equipment calibration

Order operating supplies

Water Distribution:

Avolan Lodge water shut-off and service valve locate

Miscellaneous:

Misc. USA locates

Installed new water heater at plant

Snow removal

Administration:

Prepared and Submitted December 2009 Monitoring report

Prepared and Submitted 4th quarter D/DBP report

Attended TWSA Meetings